

Product Information Bulletin		PIB: CS2015-210 Date: 1/26/2015
Products affected: CG150 CAN/USB gateway interface communicator	Subject: Obsolescence of components	

Component	Final assembly
Date of Introduction	February 2015
Customer Action	<p>If placing new orders, the new part number is 11153051.</p> <p>Some existing orders for 10104136 will need to be changed to the new part number 11153051. A customer service representative will contact you if this is the case.</p>

A component within the CG 150 CAN/USB gateway interface communicator has been made obsolete. As a result, we have found a new component and revised the model. The new model, CG150-2, will replace the CG 150 model. This will change the material number.

This change will also impact the function as you will need to use the latest version of PLUS+1 service tool v7.1.10. Only PLUS+1 service tool version 7.1.10 has the driver file to support the new CG150-2. Customers receiving their new CG150-2 will need to use PLUS+1 service tool 7.1.10 at a minimum. Driver files for the older CG150 will continue to be supported in the PLUS+1 service tool for at least 2 more years minimum.



Old Part Number	New Part Number
-----------------	-----------------

CG150 - 10104136	CG150-2 - 11153051

For questions or concerns, please contact your local Danfoss Power Solutions representative.

All Failure Mode Effects Analysis (FMEA's) and Control Plans affected by this change have been updated. Dimensional (ISIR), Capability (as required), and Measurement studies have been completed with prototypes and will have been verified with production tooling & processes before executing the change.

Copies of the quality documentation supporting this change are available for review at Danfoss Power Solutions.