


Model:322 HIPRO
Chapter 10.2.2 Jib 100X

5441081
OLP 322-4 + Jib 100X (Up to 3220256)


5441081 - OLP 322-4 + Jib 100X (Up to 3220256)				Pos	Part No	Description	Quantity
 The box are placed under the plastic cover on the column To space box. Parts placed on the JIB. 544-1081				1	3607259	CONNECTION BOX	1
				2	3602800	PRESSURE SENSOR	2
				3	3600866	TILT INDICATOR	1
				4	3751449	CDABLE	1
				5	3643875	CDABLE	1
				6	9827269	CONDUIT ENTRY	2
				7	9921290	O-RING	2
				8	9828061	NUT	2
				9	9827242	CONDUIT ENTRY	3
				10	9921265	O-RING	3
				11	9828010	NUT	3
				12	3611035	CABLE	2
				13	3643883	PLUG	1
				14	3760049	CDABLE	1
				15	3760081	HOSE	1
				16	9836055	BAND	60
				17	3742296	GUARD	1
				18	9870121	CONNECTOR	1
				19	9828192	HOLDER	3
				20	9829822	HOLDER	1

Model:322 HIPRO Chapter 10.2.2 OLP 322-4 + Jib 100X (Up to 3220256)

3600866 Tilt indicator


3600866 - Tilt indicator

Pos	Part No	Description	Quantity
1	3600866	TILT INDICATOR	1
2	9904395	BALL	1



Model:322 HIPRO
Chapter 10.2.2 OLP 322-4 + Jib 100X (Up to 3220256)

3607259
Connection box

3607259 - Connection box					Pos	Part No	Description	Quantity
					1	3601129	BOX KOPPLINGSBOX	1
					2	3617424	COVER	1
					3	9827595	SCREW	6
					4	9829814	O-RING	1
360-7259								