



Radio parts type **344**, **380**, **507** and **509** are no more available as spare parts.

If you need one of these modules you must replace also the other corresponding part with a couple of new "radio module + receiver".



FABERCOM

Replacement description for G1 radio parts

FILE: Scanreco\G1\Documenti\Comunicazioni\Radio non disponibili.cdr

DATA: 09/09/11