



## OBROTOWY PUNKT MOCUJĄCY KLASA 8

| DOR  |      | Masa  | D x E   | A    | B    | Ø    |
|------|------|-------|---------|------|------|------|
| [m]  |      | [kg]  | [mm]    | [mm] | [mm] | [mm] |
| 0°   | 90°  |       |         |      |      |      |
| 0,6  | 0,3  | 0,45  | M8x13   | 52   | 31   | 14   |
| 1,0  | 0,5  | 0,45  | M10x16  | 54   | 31   | 14   |
| 1,0  | 0,5  | 0,49  | M10x90  | 54   | 31   | 14   |
| 1,0  | 0,5  | 0,47  | M12x18  | 54   | 28   | 14   |
| 1,0  | 0,5  | 0,53  | M12x110 | 54   | 28   | 14   |
| 2,0  | 1,12 | 0,48  | M16x20  | 54   | 28   | 14   |
| 2,0  | 1,12 | 0,62  | M16x120 | 54   | 28   | 14   |
| 4,0  | 2,0  | 0,99  | M20x30  | 70   | 34   | 16   |
| 4,0  | 2,0  | 1,17  | M20x120 | 70   | 34   | 16   |
| 5,3  | 3,15 | 1,44  | M24x30  | 85   | 38   | 18   |
| 5,3  | 3,15 | 1,77  | M24x120 | 85   | 38   | 18   |
| 10,6 | 5,3  | 2,27  | M30x35  | 83   | 40   | 20   |
| 10,6 | 5,3  | 2,63  | M30x120 | 83   | 40   | 20   |
| 11,8 | 8,0  | 3,72  | M36x50  | 115  | 50   | 22   |
| 11,8 | 8,0  | 3,99  | M36x90  | 115  | 50   | 22   |
| 15,0 | 10,0 | 3,24  | M42x50  | 115  | 50   | 25   |
| 15,0 | 10,0 | 5,35  | M42x80  | 115  | 50   | 25   |
| 15,0 | 10,0 | 4,35  | M48x50  | 115  | 50   | 25   |
| 15,0 | 10,0 | 5,1   | M48x110 | 115  | 50   | 25   |
| 25,0 | 15,0 | 11,35 | M56x84  | 150  | 70   | 32   |
| 25,0 | 15,0 | 12,05 | M64x95  | 150  | 70   | 32   |

