

Tabela 1

Index	C	Gwint Prawy/Lewy*	L2	D1	D2	D3	E	A
P5	M5	Prawy	10.2		8 M5		8,2	10,2
P5L	M5	Lewy	10.2		8 M5		8,2	10,2
P6	M6x1	Prawy	12.2		10 M6x1		10,3	12,2
P6L	M6x1	Lewy	12.2		10 M6x1		10,3	12,2
P8	M8x1,25	Prawy		16	13 M8x1,25		13,3	14
P8L	M8x1,25	Lewy		16	13 M8x1,25		13,3	14
P10	M10x1,5	Prawy		20	16 M10x1,5		16,5	15,5
P10L	M10x1,5	Lewy		20	16 M10x1,5		16,5	15,5
P12	M12x1,75	Prawy		20	16 M12x1,75		16,5	15,5
P12L	M12x1,75	Lewy		20	16 M12x1,75		16,5	15,5

