




Service Bulletin 050034

Issued 06/03

For TK Torqmotor™ Seal Kit SK000167

REF. TK

SERVICE MANUAL



Thoroughly coat or pack this bearing with special grease supplied in kit.

Parker Hannifin Corporation
Hydraulic Pump/Motor Division
Snapps Ferry Road
2745 Snapps Ferry Road
Greeneville, TN 37745 USA
Tel: (423) 639-8151
Fax: (423) 787-2418
<http://www.parker.com/pumpmotor>

Item No.	Description	Part No.	Qty.
3.	Seal Ring-Commutator	032438	1
5.	Seal Ring (4 Required)	032807	5
18.	Shaft Seal	032854	1
19.	Backup Washer	028549	1
20.	Backup Ring	032851	1
23.	Dirt & Water Seal	478082	1
	Grease Pack	406018	1