



Rozmiar nominalny Lina-Ø (mm)	Wymiary według rysunku (mm)				Niezbędna ilość zacisków sztuk	Niezbędny moment dokręcenia śruby Nm
	a	d1	h1	s		
5,0	12	M 5	25	8	3	2,0
6,5	14	M 6	32	10	3	3,5
8,0	18	M 8	41	13	4	6,0
10,0	20	M 8	46	13	4	9,0
12,0	24	M 10	56	16	4	20,0
13,0	27	M 12	64	18	4	33,0
14,0	28	M 12	66	18	4	33,0
16,0	32	M 14	76	21	4	49,0
19,0	36	M 14	83	21	4	68,0
22,0	40	M 16	96	24	5	107,0
26,0	46	M 20	111	30	5	147,0
30,0	54	M 20	127	30	6	212,0
34,0	60	M 22	141	34	6	296,0
40,0	68	M 24	159	34	6	363,0